202



30 MM HOLE IN BACK TOP SIDE OF BOAT RAMP. ROUND PASSED FROM FRONT TO BACK, SEE DIAGRAM

PATH of Round



GROUND.

C 7016

DAMAGE NOT INDICATIVE of a maverick