C208



LARGE ENTRY HOLE IN RIGHT FRONT OF VEHICLE. DIRECT FIRED FROM FRONT OF VEHICLE TO REAR